EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	3	(((surface or interior) and (rough\$3 and cut \$4 and (tool or apparatus or device or machine) and rotat \$4 and (peaks or valleys or grooves or recesses or divets) and stress and (fractur\$3 or break \$3)).cim.	US- PGPUB	OR	ON	2009/04/10
L2	4	((surface or interior) and (rough\$3 or ougher\$3) and cut \$4 and (tool or appar at us or device or machine) and rotat \$4 and (peaks or valleys or grooves or valleys or grooves or fecesses or divets) and (force or stress) and (fractur\$3 or break\$3).clm.	US- PGPUB	OR	ON	2009/04/10
L3	1	2 not 1	US- PGPUB	OR	ON	2009/ 04/ 10 23:49
L4	5	(((surface or interior or portion or layer) and (roughs 3) or roughers 3) and cut \$4 and (tool or apparatus or device or machine) and rotat \$4 and (peaks or valleys or grooves or recesses or divets) and (force or stress) and (fracturs 3) or break\$3).clm.	US- PGPUB	OR	ON	2009/04/10

L5	5	((surface or interior or portion or layer) and (rough\$3 or roughen\$3) and (cut \$4 or shear\$3 or sever\$3) and (tool or apparatus or device or machine) and rotat \$4 and (peaks or valleys or grooves or recesses or divets) and (force or stress) and (fractur\$3 or break\$3)).clm.	US- PGPUB	OR	ON	2009/04/10 23:57
L6	5	((surface or interior or portion or layer) and (rough\$3 or roughen\$3) and (cut \$4 or shear\$3 or sever\$3) and (tool or apparatus or device or machine) and (spinn \$3 or rotat\$4) and (peaks or valleys or grooves or recesses or divets) and (force or stress) and (fractur\$3 or break \$3)).clm.	US- PGPUB	OR	ON	2009/04/10 23:58
L7		((surface or interior or portion or layer) and (rough\$3 or roughen\$3) and (cut \$4 or shear\$3 or sever\$3) and (tool or apparat us or device or machine) and (spinn \$3 or rotat\$4) and (peaks or valleys or grooves or recesses or divets or protuberances) and (force or stress) and (fractur\$3 or break \$3)).clm.	US- PGPUB	OR	ON	2009/04/10

\$3 or roughen\$3) and (cut\$4 or shear \$3 or sever\$3) and (tool or apparatus or device or machine) and (spinn\$3 or rotat \$4) and (peaks or valleys or grooves or recesses or divets or protuberances) and (f orce or stress) and (f ract ut\$3 or break
--

4/10/09 11:59:51 PM

C:\ Documents and Settings\ j cozart\ My Documents\ EAST\ workspaces\ Surface-RougheningMethod, wsp